

Photographs: **AMARILLO AIR TERMINAL BUILDING**




Photo 81. Concourse 30, 2nd floor, Airport Storage - General view of fireproofed beams and open web joists above suspended ceiling




Photo 82. Concourse 30, 2nd floor, Airport Storage - General view of fireproofed beams and cross bracing along perimeter wall




Photo 83. Concourse 30, 2nd floor, Airport Storage - Close-up of dust sample # 1 (top of fluorescent light fixture)




Photo 84. Concourse 30, 2nd floor, Airport Storage - View of impacted fireproofing above suspended ceiling




Photo 85. Main Terminal, Basement, Mechanical Rm - General view of fireproofed concrete beam adjacent to air handler




Photo 86. Main Terminal, Basement, Mechanical Rm - General view of delaminated fireproofed applied to wall adjacent to parts storage area




Photo 87. Main Terminal, Basement, Mechanical Rm - View of delaminated/dislodged fireproofing dust and debris on floor (in parts storage area)